

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, September 25, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)								
	learing Rough Grading Trench Excavation				\boxtimes	Pipe Assembly, Testing & Installation		
\boxtimes	Backfilling and Grade Restoration Final Grading & Stabilizati	and Grade Restoration Final Grading & Stabilization			\boxtimes	Other: Stream Crossing		
		Yes	No	N/A				
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							
3	Areas of offsite sediment deposition were observed?		\boxtimes					
Comments: • Area 1 - MP 247 station#13043+20 designated stream H-1 dewatering structure in place for stream crossing.								
Deadline: n/a								
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.								
Inspector Signature: Date:11-5-18								



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Tuesday, September 25, 2018







